



Fig. 7.13 Moody diagram. (From L. F. Moody, Trans. ASME, Vol. 66, 1944. Reproduced with permission of ASME.)
 (Note: If $e/D = 0.01$ and $Re = 10^4$, the dot locates $f = 0.043$.)